

Honda PC800 Pacific Coast

Parts list for MCS 4170 kit

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCSU 400C	Computer
2	4		M4 x 12 pan head screw
3	8		4mm flat washer
4	4		M4 Nyloc nut
5	4		8g x 3/8 self tap screw
		<u>MCS 4172</u>	<u>Vacuum actuator assembly</u>
6	1	MCS 574	Vacuum actuator
7	1	MCS 1153A	actuator bracket
	3		6 gauge x 3/8" pan head self tap screw
8	2	Hose Clamp 16	Hose clamps
		<u>MCS 1155</u>	<u>Carburettor arm assembly</u>
9	1	MCS 1155A	Carburettor arm
10	1	MCS 025A	4mm shouldered screw
11	1	MCS 025B	5mm eye bead chain connector
12	1		4mm flat washer
13	1		M4 Nyloc nut
14	1	MCS 025C	Bead chain and coupling
		<u>MCS 1156</u>	<u>Flexible cable bracket assembly</u>
15	1	MCS 1156A	Actuator flexible cable bracket
16	3	MCS 024A	Flexible cable clamp (2 spares)
17	1		M6 x 16 plated bolt
18	3		6mm plated flat washer
19	1		M6 Nyloc nut
		<u>MCS 1157</u>	<u>Vacuum hose assembly</u>
20	1	MCS 032	Vacuum stop valve 4mm Vacuum hose
21	1	MCSU 401	Wiring loom
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			Tach sensor wire (yellow wire)
d			Speed sensor connectors (co-axial wire)
e			Actuator plug (4 pin)
f			Power & brake sensor wires (orange and grey wires)
g			Ground connector (black wire)
h			Neutral sensor wire (blue wire)
i			Switch plug (6 pin)
		<u>MCS 4174</u>	<u>Control switch assembly</u>
22	1	MCS 820	Control Switch
23	1	MCS 4174A	Switch bracket
	4		4 gauge x 1/2" pan head SS self tap screw
	1		100mm cable tie
24	1	MCS 4174B	Switch bracket backing plate

25	2		4mm plated flat washer
26	2		M4 x 6 pan head screw
		<u>MCS 1151</u>	<u>Speed sensor assembly</u>
27	1	MCS 1151A	Speed sensor bracket
28	1	MCS 027	Speed sensor
29	1		M6 Nyloc nut
30	3		6mm plated flat washer
	6	MCS 039	magnet, 6mm dia x 6mm long
	10		100mm cable tie
	10		200mm cable tie
			Information, Set up and Operation Manual
			Operation and User Manual
			Installation Manual
			Trouble shooting guide
	1	JD020	Brake switch connector 2way
	3	H2858	Terminals for above
	1	JD021	Brake switch connector 2 way
	3	H3739	Terminals for above
	3	H 2590	4.8mm QC receptacle (speed sensor connector)
	2	H 2088	Insulator for above
	10cm	HST 3	Heat shrink tube
	10cm	HST 6	Heat shrink tube
	2	H2833	Tach sensor terminal (piggy back)
	1	H1135	Insulator for above
	2	H 2590	4.8mm QC receptacle terminal (clutch switch connector)
	1	H 2088	Insulator for above
	2	H 2571	4.8mm QC tab terminal (clutch switch connector)
	1	H 2805	Insulator for above
	2	H1863	6mm ring terminal (ground connection)
	20	AMP 3-1447221-4	Computer plug terminals
	2	AMP 4-1437284-3	Computer plug blanking plugs
	5		Wire tap connectors ('Scotchlock' or 'Quick tap' connectors)

