

HONDA CBF1000 from 2008

Parts list for MCS 4700 kit

Item	Qty	Part Number	Description
1	1	MCSU 400C	Computer
2	3		8cm length of foam mounting tape
3	1	MCS 001	Foam mounting block
		<u>MCS 4702</u>	<u>Vacuum actuator assembly</u>
4	1	MCS 574	Vacuum actuator (triple solenoid)
5	1	MCS 4702A	Actuator mounting bracket
	3		6g x 3/8" self tap screw
6	2	HoseClamp8	Hose clamp 8~22mm
		<u>MCS 4707</u>	<u>Vacuum hose assembly</u>
7	1	MCS 032	Vacuum stop valve
8	1	MCS 031	4mm Vacuum Tee connector 4mm Vacuum hose
9	1	<u>MCS 4701</u>	<u>Wiring harness</u>
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			Tach sensor (yellow wire)
d			Speed sensor (co-axial wire)
e			Actuator plug (4 pin)
f			Power & brake sensor (orange and grey wires)
g			Ground connector (black wire)
h			Neutral sensor (blue wire)
i			Control switch plug (6 pin)
		<u>MCS 4704</u>	<u>Control Switch assembly</u>
10	1	MCS 820	Control Switch
11	1	MCS 830B	Switch bracket
	4		4 gauge x 1/2" pan head self tap screw
		<u>MCS 4705</u>	<u>Cable Interface Unit (CIU) assembly</u>
13	1	MCS 4705A	CIU housing
14	1	MCS 003F	Actuator spool
15	1	MCS 4706	Dual spool
16	1	MCS 003H	Bush
17	1	MCS 003K	End Cap
18	1		M5 x 50 pivot bolt
19	1		Pivot nut M5 Nylok nut
20	2		5mm plated flat washer
21	1		M4 x 10 pan head screw (actuator cable retainer)
22	1	MCS 4705B	CIU mounting bracket
23	1		M6 x 35 bolt
24	2		6mm flat washer
25	1	MCS 4708	Throttle grip cable (Honda Part # 17910-MFA-D00)

26	1	<u>MCS 4703</u>	<u>Speed sensor assembly</u>
27	1	MCS 4703A	Speed sensor bracket
28	1		M8 x 35 high tensile bolt
29	1		8mm flat washer
30	2	MCS 027	Speed sensor
31	1		6mm flat washer
	1		M6 Nylok nut
	8	MCS 039	magnet, 6mm dia x 6mm long (2 spare)
	10		100mm cable ties
	15		150mm cable ties
	8		300mm cable ties
	2 ml		Throttle cable oil (Singer industrial sewing machine oil)

Information, Set up and Operation Manual
 Operation and User Manual
 Installation Manual
 Trouble shooting guide

