

HONDA CBR1100XX Carburettor

Parts list for MCS 4200 kit

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCSU 400C	Computer
2	1	MCS 001	Foam mounting block
		<u>MCS 4202</u>	<u>Vacuum actuator assembly</u>
3	1	MCS 574	Vacuum actuator
4	1	MCS 1473A	Actuator bracket
	3		6g x 3/8" pan head self tap screws
		<u>MCS 4207</u>	<u>Vacuum hose assembly</u>
5	2	MCS031	'T' connector
6	2	MCS 032	Vacuum stop valve
7	2	MCS 051	Vacuum port adaptor (M5 thread) and sealing washer 4mm Vacuum hose
8	1	MCS 401	Wiring loom
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			Tach sensor wire (yellow wire)
d			Speed sensor connectors (co-axial wire)
e			Actuator plug (4 pin)
f			Power & brake sensor wires (orange and grey wires)
g			Ground connector (black wire)
h			Neutral sensor wire (blue wire)
i			Control switch plug (6 pin)
		<u>MCS 4204</u>	<u>Control switch assembly</u>
9	1	MCS 820	Control switch
10	1	MCS 830C	Switch bracket
	4		4 gauge x 1/2" pan head self tap screw
		<u>MCS 1175</u>	<u>Cable Interface Unit (CIU) assembly</u>
12	1	MCS 1175A	CIU housing
13	1	MCS 003M	Actuator spool
14	1	MCS 1176	Dual spool
15	1	MCS 003H	Bush
16	1	MCS 003J	End Cap
17	2	MCS 1175B	Foam pads
18	1		M5 x 45 plated bolt (pivot bolt)
19	1		M5 Nyloc nut
20	2		5mm plated flat washer
21	2	MCS 003P	Mounting clip
22	2		M6 x 16 bolt
23	2		6mm flat washer
24	1		M4 x 6 pan head screw (actuator cable retainer)
25	1	MCS 150	Carburettor cable

26	<u>MCS 1171</u>	<u>Speed sensor assembly</u>
1	MCS 1171A	Speed sensor bracket
1	MCS 027	Speed sensor
1		M6 Nyloc nut
2		6mm plated flat washer
2	MCS 045	magnet, 6mm dia x 4.5mm long
10		100mm cable ties
6		200mm cable ties
2		300mm cable ties

Information, Set up and Operation Manual
 Operation and User Manual
 Installation Manual
 Trouble shooting guide

Electrical terminals supplied for Universal Wiring Loom (ONLY supplied if Custom Loom is NOT supplied)

1	JD020	Brake switch connector 2way
3	H2858	Terminals for above
1	JD021	Brake switch connector 2 way
3	H3739	Terminals for above
3	H 2590	4.8mm QC receptacle (speed sensor connector)
2	H 2088	Insulator for above
10cm	HST 3	Heat shrink tube
10cm	HST 6	Heat shrink tube
2	H1972	Tach sensor receptacle terminal
1	H1135	Insulator for above
2	H1192	Tach sensor tab terminal
1	H2805	Insulator for above
2	H2590	Clutch switch receptacle terminal
1	H2088	Insulator for above
2	H2571	Clutch switch tab terminal
1	H2805	Insulator for above
2	H1863	6mm ring terminal (ground connection)
5		Wire tap connectors ('Scotchlock' or 'Quick tap' connectors)
20	AMP 3-1447221-4	Computer plug terminals
2	AMP 4-1437284-3	Computer plug blanking plugs

