

# HONDA GL1100 Gold Wing

## Part list for MCS 4210A kit

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCSU 400C	Computer
2	4		M4 x 10 pan head screw
3	4		4mm flat washer
4	4		M4 Nyloc nut
5	4		8g x 3/8 self tap screw
6	1	MCS 048E	Self adhesive pad
	1	<u>MCS 4212</u>	<u>Vacuum actuator assembly</u>
7	1	MCS 574	Vacuum actuator
8	1	MCS 1273A	Mounting bracket
	3		6g x 3/8" pan head self tap screws
9	2	Hose Clamp 6	Hose clamp 8-22mm dia
	1	<u>MCS 1277</u>	<u>Vacuum hose assembly</u>
10	1	MCS 032	Vacuum stop valve
11	1	MCS 051	Vacuum port fitting
12	1	MCS 051A	Sealing washer
13			4mm Vacuum hose
14	1		MCSU 401 Wiring loom
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			Tach sensor wire (yellow wire)
d			Speed sensor connectors (co-axial wire)
e			Actuator plug (4 pin)
f			Power & brake sensor wires (orange and grey wires)
g			Ground connector (black wire)
h			Neutral sensor wire (blue wire)
i			Switch plug (6 pin)
		<u>MCS 4214</u>	<u>Switch assembly</u>
15	1	MCS 820	Switch
16	1	MCS 830C	Switch bracket
	4		4 gauge x 1/2" pan head SS self tap screw
	1		100mm cable tie
17	1		M6 x 30 high tensile bolt
18	1		6mm flat washer
		<u>MCS 1275</u>	<u>Cable Interface Unit (CIU) assembly</u>
20	1	MCS 1275A	CIU housing
21	1	MCS 003M	Actuator spool
22	1	MCS 1276	Dual spool
23	1	MCS 003H	Bush
24	1	MCS 003J	End Cap
25	1		M5 x 45 bolt
26	1		M5 Nyloc nut
27	2		5mm plated flat washer
28	1		M4 x 6 pan head screw (actuator cable retainer)

29	1	MCS 1275B	CIU mounting bracket
30	2		M6 x 16 bolt
31	2		6mm flat washer
32	1	MCS 1278	Carburettor cable
32a	1	MCS 003R	Tab locating washer
	1	<u>MCS 1271</u>	<u>Speed sensor assembly</u>
33	1	MCS 1271A	Speed sensor bracket
34	1		M8 x 40 high tensile bolt
35	6		8mm plated flat washers
36	1	MCS 027	Speed sensor
	1		M6 Nyloc nut
	3		6mm plated flat washer
37	1	MCS 073	magnet assembly
38	2		8mm plated flat washer
	10		100mm cable ties
	8		200mm cable ties
	6		300mm cable ties
	1	JD020	Brake switch connector 2way
	3	H2858	Terminals for above
	1	JD021	Brake switch connector 2 way
	3	H3739	Terminals for above
	3	H1192	6mm QC tab (brake switch connector)
	2	H2805	Insulator for above
	3	H1972	6mm QC receptacle (brake switch connector)
	2	H1135	Insulator for above
	3	H 2590	4.8mm QC receptacle (speed sensor connector)
	2	H 2088	Insulator for above
	10cm	HST 3	Heat shrink tube
	10cm	HST 6	Heat shrink tube
	2	H2833	Tach sensor terminal (piggy back)
	1	H1135	Insulator for above
	2	H1863	6mm ring terminal (ground connection)
	20	AMP 3-1447221-4	Computer plug terminals
	2	AMP 4-1437284-3	Computer plug blanking plugs
	5		Wire tap connectors ('Scotchlock' or 'Quick tap' connectors)
			Information, Set up and Operation Manual
			Operation and User Manual
			Installation Manual
			Trouble shooting guide

