

Kawasaki Z1000GTR Concours

Part list for MCS 4230A kit

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCSU 400C	Computer
2	4		M4 x 10 pan head screw
3	4		4mm flat washer
4	4		M4 Nyloc nut
5	4		8g x 3/8 self tap screw
	1	<u>MCS 4232</u>	<u>Vacuum actuator assembly</u>
6	1	MCS 574	Vacuum actuator
7	1	MCS 1103A	Mounting bracket
	3		6g x 3/8" pan head self tap screws
	1	<u>MCS 4237</u>	<u>Vacuum hose assembly</u>
8	1	MCS 031	Vacuum 'T' piece
9	2	MCS 032	Vacuum stop valve
10			4mm Vacuum hose
11	1	MCSU 401	Wiring loom
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			Tach sensor wire (yellow wire)
d			Speed sensor connectors (co-axial wire)
e			Actuator plug (4 pin)
f			Power & brake sensor wires (orange and grey wires)
g			Ground connector (black wire)
h			Neutral sensor wire (blue wire)
i			Switch plug (6 pin)
		<u>MCS 4234</u>	<u>Switch assembly</u>
12	1	MCS 820	Switch
13	1	MCS 830D	Switch bracket
	4		4 gauge x 1/2" pan head SS self tap screw
	1		100mm cable tie
14		<u>MCS 4235</u>	<u>Cable Interface Unit (CIU) assembly</u>
15	1	MCS 4235A	CIU housing
16	1	MCS 003F	Actuator spool
17	1	MCS 1106	Dual spool
18	1	MCS 003H	Bush
19	1	MCS 003K	End Cap
20	1		M5 x 45 bolt
21	1		M5 Nyloc nut
22	2		5mm plated flat washer
23	1		M4 x 10 pan head screw (actuator cable retainer)
24	1	MCS 1107	CIU mounting bracket
25	2	Hoseclamp 20	Hose clamp

26	1	MCS 300	Carburettor cable
	1	<u>MCS 1101</u>	<u>Speed sensor assembly</u>
27	1	MCS 1101A	Speed sensor bracket
28	1	MCS 027	Speed sensor
29	1		M6 Nyloc nut
30	2		6mm plated flat washer
	6	MCS 039	Magnet, 6mm dia x 6mm long
	10		100mm cable ties
	10		200mm cable ties
	2	MCS 430	Throttle cable removal and installation tool
	3	H2782	Brake switch 4mm male bullet terminal
	2	H2805	Insulators for above
	3	H2743	Brake switch 4mm female bullet terminal
	2	H2806	Insulators for above
	3	H 2590	4.8mm QC receptacle (speed sensor connector)
	2	H 2088	Insulator for above
	10cm	HST 3	Heat shrink tube
	10cm	HST 6	Heat shrink tube
	2	H2833	Tach sensor terminal (piggy back)
	1	H1135	Insulator for above
	2	H2590	Clutch switch receptacle terminal
	1	H2088	Insulator for above
	2	H2571	Clutch switch tab terminal
	1	H2805	Insulator for above
	2	H1863	6mm ring terminal (ground connection)
	20	AMP 3-1447221-4	Computer plug terminals
	2	AMP 4-1437284-3	Computer plug blanking plugs
	5		Wire tap connectors ('Scotchlock' or 'Quick tap' connectors)
			Information, Set up and Operation Manual
			Operation and User Manual
			Installation Manual
			Trouble shooting guide

