

# HONDA NT700V Deauville

## Parts list for MCS 4370 kit

| <u>Item</u> | <u>Qty</u> | <u>Part Number</u> | <u>Description</u>                               |
|-------------|------------|--------------------|--|
| 1           | 1          | MCSU 400C          | Computer   |
| 2           | 1          | MCS 001            | Foam mounting block                              |
|             |            | <u>MCS 4372</u>    | <u>Vacuum actuator assembly</u>                  |
| 3           | 1          | MCS 574            | Vacuum actuator (triple solenoid)                |
| 4           | 1          | MCS 4372A          | Actuator mounting bracket                        |
|             | 3          |                    | 6g x 3/8" self tap screw                         |
|             |            | <u>MCS 4377</u>    | <u>Vacuum hose assembly</u>                      |
| 5           | 2          | MCS 032            | Vacuum stop valve                                |
| 6           | 4          | MCS 031            | Vacuum 'T' connector                             |
| 7           | 3          | MCS052             | Vacuum restrictor                                |
| 8           |            |                    | 4mm Vacuum hose                                  |
| 9           | 1          | MCS 071            | Vacuum reservoir                                 |
| 10          | 5          |                    | Foam mounting tape, 6cm long                     |
| 11          | 2          |                    | 8g x 1/2 pan head self tap screw                 |
| 12          | 2          |                    | 5mm flat washer                                  |
| 13          | 1          | MCS 4371           | Wiring loom                                      |
| a           |            |                    | Computer plug (26 pin)                           |
| b           |            |                    | Fuse holder (3 amp fuse)                         |
| c           |            |                    | Tach sensor (yellow wire)                        |
| d           |            |                    | Speed sensor (black co-axial wire)               |
| e           |            |                    | Actuator plug (4 pin)                            |
| f           |            |                    | Power & brake sensor (orange and grey wires)     |
| g           |            |                    | Ground connector (black wire)                    |
| h           |            |                    | Neutral sensor (blue wire)                       |
| i           |            |                    | Switch plug (6 pin)                              |
| 14          | 1          | MCS 820            | Control Switch                                   |
| 15          | 1          | MCS 830B           | Switch bracket                                   |
|             | 4          |                    | 4 gauge x 1/2" pan head SS self tap screw        |
|             |            | <u>MCS 4375</u>    | <u>Cable Interface Unit (CIU) assembly</u>       |
| 17          | 1          | MCS 4375A          | CIU housing                                      |
| 18          | 1          | MCS 003F           | Actuator spool                                   |
| 19          | 1          | MCS 4376           | Dual spool                                       |
| 20          | 1          | MCS 003H           | Bush   |
| 21          | 1          | MCS 003K           | End Cap  |
| 22          | 1          |                    | M5 x 45 bolt                                     |
| 23          | 1          |                    | M5 Nyloc nut                                     |
| 24          | 2          |                    | 5mm plated flat washer                           |
| 25          | 1          |                    | M4 x 10 pan head screw (actuator cable retainer) |
| 26          | 4          | MCS4375B           | Foam pads  |
| 27          | 1          | MCSCC 100          | Carburettor cable                                |

|    |    |                 |                              |
|----|----|-----------------|------------------------------|
|    |    | <u>MCS 4373</u> | <u>Speed sensor assembly</u> |
| 28 | 1  | MCS 4373A       | Speed sensor bracket         |
| 29 | 1  | MCS 027         | Speed sensor                 |
| 30 | 2  |                 | 6mm flat washer              |
| 31 | 1  |                 | M6 Nyloc nut                 |
|    | 6  | MCS 039         | 6mm dia x 6mm long magnet    |
|    | 10 |                 | 100mm cable ties             |
|    | 10 |                 | 150mm cable ties             |

Information, Set up and Operation Manual  
 Operation and User Manual  
 Installation Manual  
 Trouble shooting guide

